



INNOVATIVE IDEAS EXCEPTIONAL DESIGN UNMATCHED CLIENT SERVICE Springfield Lake No. 1 Outlet Structure & Channel Study Task B – Preliminary Plan

APPENDIX B – Field Walk Photo Log – August 1, 2023

























There is 1 steel pipe between the bridges at STA 111+80 and 112+55 and the channel is 10 ft wide concrete walls.













There is a 6" PVC pipe at STA 20+50



A-15










A-19


















A-27











A-32







A-35



After road crossing at Conceptual Plans STA 51+00 creek is 12ft wide lined with concrete





Photograph No. 75 Conceptual Plans STA 56+00 12" metal pipe just past county line



INNOVATIVE IDEAS EXCEPTIONAL DESIGN UNMATCHED CLIENT SERVICE Springfield Lake No. 1 Outlet Structure & Channel Study Task B – Preliminary Plan

APPENDIX C – Preliminary Waters Investigation Figures

FEMA Village of Lakemore Flood Risk Map


National Wetlands Inventory Map

Natural Resources Conservation Service – Custom Soil Resource Report Soil Map

Site Visit Photo Log

Figure 1 – Springfield Lake Possible WOTUS

Flood Risk Map: Cuyahoga River Watershed



MAP SYMBOLOGY












Springfield Lake



National Wetlands Inventory (NWI) This page was produced by the NWI mapper

Riverine

Freshwater Pond

Estuarine and Marine Wetland

